



CHLORINE MEASUREMENT (WITHOUT pH)



CHLORINE AND pH MEASUREMENT (TEMPERATURE USED FOR COMPENSATION ONLY)



ANALOGUE OUTPUT SIGNALS

OUT.CLAMP	OUTPUT	
12 13	1	CHLORINE 1
14 15	2	CHLORINE 2 / pH
16 17	3	AR.AVERAGE/CONTROLLER 2
18 19	4	CONTROLLER 1

ANALYZER-PROBE CONNECTIONS, CHLORINE AND pH MEASUREMENT

INPUT CLAMP	MPC66	PROBE	
20	VSTUP 1	20	CHLORINE 1
21	VSTUP 1	19	CHLORINE 1
22	VSTUP 2	18	pH
23	VSTUP 2	17	pH

PROBE SPR42 , PK41

z	GREEN
č	BLACK
b	WHITE
r	RED
me	MAIN ELECTRODE
re	REFERENCE ELECTRODE