


ORP AND pH MEASUREMENT



me	MAIN ELECTRODE
re	REFERENCE ELECTRODE

ANALOGUE OUTPUT SIGNALS

OUT.CLAMP	OUTPUT	
12 13	1	ORP 1
14 15	2	ORP 2 / pH
16 17	3	TEMPERATURE 1/AR.AVERAGE/CONTROLLER 2
18 19	4	TEMPERATURE 2/CONTROLLER 1

ANALYZER - PROBE CONNECTIONS

INPUT CLAMP	MRP66	PROBE		
20	INPUT 1	20	ORP 1	PROBE SPR42, PK41
21	INPUT 1	19	ORP 1	
22	INPUT 2	18	pH	
23	INPUT 2	17	pH	